



Model

Version

ZS8

- 1A**
 - 1. Delete RST PU RES.
 - 2. Change C5244 form 0.1u to 1u for FAE suggerst.
- 1/22/2014
 - 3. Modify CN17 symbol.
- 1/22/2014
 - 4. Swap I2C
- 2A**
 - 5. Add EMI filter on USB trace.
 - 6. Change CN5027 PN, pindefine.
 - 7. Change R5692,R6005,R6006,R6007,R6008,R6009 from 91ohm to 90.9ohm.
- 3/24/2014
 - 8. Modify CN5046 pindefin(+3V3 add 1 pin)
 - 9. Reserve R10 on VDD_SD
- 2B**
 - 10. Add R1, R2 colay on USB+,-
- 4/21/2014
 - 11. Mount C5548,C5549,C5550,C5551,C5247 2.7P, unmount D5006,D5007,D5008,D5009,D5010,D5011,D5012
- 4/23/2014
- 3A**
 - 12. Change L1 footprint
- 6/16/2014
- 6/16/2014
 - 13. Change CN5046 footprint
- 3B**
 - 14. Change 0 ohm to shortpad(R12,R5686,R5690,R5691,R10)
- 8/4/2014
- 8/13/2014
 - 15. Modify SD0-D3,CLK,CD#,CMD resistor location.
- 3C**
 - 16. Add LDO for high speed SD card read speed fail issue.
- 8/19/2014
- 8/20/2014
 - 17. unmount C5236,C5235; R429 change to 0603 size